## Field Remedy: 2595

Subject: Radio - CD does not eject

Models:		Engines:	Option:
Astra-J 2010,Meriva-B 2010,Insignia 2010		All,All,All	
Complaint:	Radio does not eject CD/DVD eventhough eject mechanism is audible.		
Cause:	Production deviation on radio face plate.		

Modified face plates are implemented in production since CW51/2009.

## Remedy:

**Production:** 

********************		
*	Technical Service Bulletin is invalid. *	
*	*	
*	Recommended Technical Service Bulletin does not work. *	
* *	********************	

FunctionalGroup: N - Electrical Equipment **Complaint Group:** 08 - Hard to operate,13 - No/Poor Function,17 - Poor Design **Trouble Code:** 

© 2010 ADAM OPEL AG. All Rights Reserved. The reproduction, distribution or modification is not permitted.