

**#15-E-3014: F40, M32 Transmission - Hard or impossible to shift gears - (2015-01-22)**

**Subject:**

Make:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Opel, Vauxhall	Zafira-C	2012	2012	C2000001	C2060162		F40, M32-6
Opel, Vauxhall	Astra-J	2012	2012	CG000001	CG083108		F40, M32-6
Opel, Vauxhall	Astra-J	2012	2012	C8000001	C8064048		F40, M32-6
Opel, Vauxhall	Astra-J	2012	2012	C1000001	C1079851		F40, M32-6
Opel, Vauxhall	Insignia	2012	2012	C1000001	C1079721		F40, M32-6
<b>Condition</b>	Shifter cable frozen.						
<b>Cause</b>	Insufficient end cap sealing.						
<b>Production</b>	Improved cables have been introduced in production with the above listed VIN's.						

**Correction**

In case of customer complaint install improved shift cables.

**Working Procedure:**

Please install new shift cables according to the relevant Service Instruction on Tis2Web.

<b>Service Part:</b>		
Please order spare part according to EPC.(The shift cables provided by P&A are the improved parts).		
<b>Labor Time:</b>	<b>Description</b>	<b>Hours:</b>
8440140	Manual Transmission Shift Lever and Selector Lever Cable Replacement	See labour time section in Tis2Web.

The regular Warranty and Policy Procedures will apply.

<b>Bulletin Version</b>	2
<b>Modified</b>	20-Jan-2015: Replaced labour code with GLC 8440140.